

Test Report No. SHAMLP1803891501 Date: 09 Mar 2018 Page 1 of 4

POMA INDUSTRIAL (SHANGHAI) CO., LTD

5F, Building A, NO.508, Chundong Road, Minhang District, Shanghai, China

The following sample(s) was/were submitted and identified on behalf of the clients as: Thermal Transfer

Ribbon

SGS Job No.: SHIN1803011936PC - SH

Product Specification: Wax/RESIN(UR217)

Manufacturer : POMA Brand : POMA

Date of Sample Received: 05 Mar 2018

Testing Period: 05 Mar 2018 - 09 Mar 2018

Test Requested: Selected test(s) as requested by client.

Test Method: Please refer to next page(s).

Test Results: Please refer to next page(s).

Signed for and on behalf of SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.

Helen Liu

Approved Signatory

Hele Lin



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions/Terms

or email: CN_Doccheck@sgs.com

13rdBuilding,No.889 Yishan Road Xuhui District, Shanghai China 200233 tE&E (86–21) 61402553 f E&E (86–21)64953679 www.sgsgroup.com.

31⁶Building,No.889 Yishan Road Xuhui District,Shanghai China 200233 中国•上海•徐汇区宜山路889号3号楼 邮编: 200233

tHL (86–21) 61402594 fHL (86–21)61156899



Test Report

No. SHAMLP1803891501

Page 2 of 4

Date: 09 Mar 2018

Test Results:

Test Part Description:

Specimen No. SGS Sample ID Description SHA18-038915.001 Black solid film SN₁

Remarks:

- (1) 1 mg/kg = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Halogen

Test Method: With reference to EN 14582: 2016, analysis was performed by IC.

Test Item(s)	<u>Unit</u>	<u>MDL</u>	<u>001</u>
Fluorine (F)	mg/kg	50	ND
Chlorine (CI)	mg/kg	50	ND
Bromine (Br)	mg/kg	50	ND
lodine (I)	mg/kg	50	ND



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions/Terms

3rd Building, No. 889 Yishan Road Xuhui District, Shanghai China 200233 中国・上海・徐汇区宜山路889号3号楼 邮編: 200233 t E&E (86-21) 61402553 f E&E (86-21)64953679 www.sgsgroup.com.cn t HL (86-21) 61402594 f HL (86-21) 61156899



Test Report

No. SHAMLP1803891501


Page 3 of 4

Date: 09 Mar 2018

ATTACHMENTS

Halogen Testing (oxygen bomb) Flow Chart

- 1) Name of the person who made testing: Kevin Xu
- 2) Name of the person in charge of testing: Sisily Yin





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions/Terms




Test Report

No. SHAMLP1803891501

Page 4 of 4

Date: 09 Mar 2018

Sample photo:



SGS authenticate the photo on original report only

*** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions/Terms